



**OFFICE OF THE SHERIFF
COUNTY OF NIAGARA**
5526 NIAGARA STREET EXT.
P.O BOX 496
LOCKPORT, NEW YORK 14095-0496

James R. Voutour
Sheriff
Michael J. Filicetti
Undersheriff
(716) 438-3370

Activity Address Code of Reporting Agency (DODAAC): 2YT05K
Reporting POC:

CASANDRA RADIG-MADDEN
1033 PROGRAM, AIRCRAFT LEAD
74 N. WASHINGTON AVE
BATTLE CREEK, MI 49037
(269) 961-7657
(269)961-4431 (FAX)
CASANDRA.RADIG-MADDEN@DLA.MIL

**Custodial POC: (Law Enforcement Agency POC information:
NAME/PHONE/EMAIL/PHYSICAL LOCATION OF AIRCRAFT)**

Lt. Ronald Steen
(716)438-3346
Ronald.steen@niagaracounty.com
Aircraft location: Niagara County Sheriff's Office
5526 Niagara St. Extension
Lockport, NY 14094

Manufacturer: Bell

Make: OH-58

Model: C

Manufacture Date: 01/01/1968

Serial Number(s): 68-16724

Are Major Components Missing?
☒ Yes or ☐ No

If yes:
☒ Engine
☒ Avionics

☒ Other

Original Acquisition Cost: \$ 190,817

DEMIL Code:

(A, B, C)

Is the Dataplate Available:

☒ Yes or ☐ No

Are Historical and Maintenance Records Available:

☒ Yes or ☐ No

Has aircraft been certificated by the Federal Aviation Administration:

☒ Yes or ☐ No

Has aircraft been maintained to Federal Aviation Administration standards:

☐ Yes or ☒ No

Has the aircraft been used for non-flight purposes:

☒ Yes or ☐ No

If yes:

☐ Ground Training

☐ Static Display

☐ Extensive disassembly and re-assembly

☐ Repeated burning for fire-fighter training

☒ Extensive cannibalization

Description: The engine, main rotor blades, tail rotor blades, transmission, mast, avionics, and empennage have all been removed from the aircraft. The total time on the airframe is 3714 hours.

Condition:

☐ New/Unused

☐ Usable

☐ Repairable

☐ Salvage

☒ Scrap